



Associated British Ports - Lowestoft

**No 37
2017**

NOTICE TO MARINERS

LOWESTOFT - NORTHEAST APPROACHES, EAST CARDINAL 'SEWER' BUOY -UNLIT

Mariners and Port Users are advised that the East Cardinal 'Sewer' Buoy, in position 52° 28.89'N, 001° 46.24'E, is unlit.

The buoy remains in position, so mariners are requested to navigate with caution in darkness in the vicinity of the unlit buoy.

Confirmation will be provided when the light has been reinstated.

Please contact Lowestoft Port Control, VHF Ch14, or Tel. 01502 572286, if further information is required.

Harbour Master

19th December 2017

Notices to Mariners Currently in Force: 2006 No.5 **2007** No.13 **2008** No.39 **2009** No.19 **2011** No.7, No.10, No.19 **2012** No.3, **2013** No.17, No.19, **2015** No.10, No.24 **2016** No.12, No.18, **2017** No.1, No.5, No.9a, No.12, No.22, No.24, No.32, No.34, No.35, No.36, No.37